

Development Center Project

Construction Update



Painting had started



Duct Insulation being Installed



Chapel Ceiling Framed

Current Activities:

- Framing of walls Continues
- Sheetrock walls & Mud & Tape continues
- Painting Started
- Exterior Demolition has started
- MEP rough-in continues (insulation and pulling wire)

Upcoming Activities:

- Frame walls Completes
- Hanging of sheetrock Completes
- Mud & Tape sheetrock to Completes
- Painting Continues
- Work outside to continue
- MEP rough-in continues