

ISSUE of October 21, 2021

Development Center Project

Construction Update




Duct Rough-in at old high school room

Current Activities:

- Overhead Rough-in Continues
- Concrete pour back Completed
- Wall Layout Continues
- Framing of walls started



2nd Level Wall Framing



1st level Overhead Duct insulation and ceiling wires

Upcoming Activities:

- Continue MEP Overhead Rough-in
- Layout of walls Complete
- Frame walls Continues
- In wall rough in starts
- Hang Sheetrock to start