

# Development Center Project

## Construction Update



Millwork Continues



Chapel Ceiling



Flooring Install Continues

### Current Activities:

- Painting Continues
- MEP ceiling trim out Continues
- Millwork Tops installing
- Ceiling Tile Continues
- Tile work Completes
- Carpet & Sheet good flooring Continue
- Glass installing

### Upcoming Activities:

- Painting Continues
- Millwork Tops Completes
- Test & Balance of air systems
- Ceiling Tile Completes
- Flooring Completes
- MEP trim Completes
- Final Inspections