

ISSUE 21 April 21, 2022

Development Center Project

Construction Update









Flooring Installation

Current Activities:

- Painting Continues
- MEP ceiling trim out Continues
- Millwork Tops installing
- Ceiling Tile boarders started
- Tile work stated
- Carpet & Sheet good flooring started



Upcoming Activities:

- Painting Continues
- Millwork Tops Continue
- Test & Balance of air systems
- Ceiling Tile continues
- Flooring continues
- MEP trim out to start